Under the Paperwork Reduction Act of 1995, no persuina are required to respond to a collection of information unless it displays a valid DMB correct number. (Also Form P"O-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. 7 426 900 APPLICATION NO.: 10/716,729 ISSUE DATE Sep. 23, 2008

INVENTOR(S) : Brcka

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below.

In the Abstract, at line 4, "prepare substrates for, and to process substrates by applying," should read -- prepare substrates for, and to process substrates by, applying---

In Column 1, line 16, "sources, which utilizing" should read --sources, which utilize--.

In Column 2, line 41, "the ICP sources with a spiral coil produces" should read -- ICP sources with spiral coils produce ---

In Column 3, line 56, "source is provided." should read -- source are provided.--.

In Column 4, line 59, "FIG 6D, is a slot" should read -- FIG 6D is a slot--.

In Column 7, line 59, "which are practical and may be" should read -- which are practical may

In Column 7, line 61, "I-ESIC device." should read --i-ESIC device.--.

In Column 8, line 7, "Ceep" should read -- Cern--.

In Column 9, line 11, "FIG. 6A-6B show" should read -- FIGS. 6A-6B show--.

In Column 9, lines 24-25, delete "Express Mail No. EV354971157US,".

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Wood, Herron & Evans, L.L.P. 441 Vine St., Suite 2700

Cincinnati, OH 45202

VA 22313-1450.

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file The sufficient of manifolding in Equations by 30 PCN 6464, 1943, min 1949. Here manifold is required to begin to recent a period and or the USPTO is crosses) an application. Confidentially is governed by \$6 USQ, 192 and \$7 CR 114 This collection is estimated to see 10 hour to origine including gate-error, preparing, and submitted to the completed application form to the USPTO. Time will vary depending upon the including cases. Any Company Instituting (per mong), impaning, and moderning are company approximated approximation of the Ord Company and September of the Company and Com FORWS TO THIS ADDRESS SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.: 7,426,900

Issue Date: September 23, 2008 Serial No.: 10/716.729

Applicant: Breka

Title: INTEGRATED ELECTROSTATIC INDUCTIVE COUPLING FOR

PLASMA PROCESSING

Attorney Docket; TAZ-240

Confirmation No.: 6314

Cincinnati, Ohio 45202 Electronically Filed August 28, 2009

Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir

REQUEST FOR CERTIFICATE OF CORRECTION (37 CFR §§ 1.322(a), 1.323)

It is respectfully requested that a Certificate of Correction be issued for the aboveidentified patent. The patent contains errors that occurred through the fault of the U.S. Patent and Trademark Office. The patent also contains errors in the specification and Abstract that occurred by Applicant.

Form PTO/SB/44 outlining the corrections to be made is submitted herewith.

Applicant submits herewith the fee of \$100 due as a result of this request. If any deficiencies or credits are necessary to complete this communication, please apply them to Deposit Account No. 23-3000

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By: / Joseph R. Jordan / Joseph R. Jordan, Reg. No. 25,686

2700 Carew Tower 441 Vine Street Cincinnati, OH 45202 (513) 241-2324 (telephone) (513) 241-6234 (facsimile)